#SAFERCARSFORINDIA



SUZUKI MARUTI ALTO - NO AIRBAGS



ADULT OCCUPANT PROTECTION



CAR DETAILS

TESTED MODELSUZUKI MARUTI
ALTO 800, RHDBODY TYPE4 DOOR CITY CARCRASH TEST WEIGHTKG 924YEAR OF PUBLICATION2014

FRONT PASSENGER

DRIVER

CHILD RESTRAINTS

| | CHILD RESTRAINT | HEAD / CHEST | CRS TYPE | ADJUST | POSITION |
|--------------------|-----------------|------------------|----------|--------|----------|
| 18 MONTH OLD CHILD | CHICCO AUTOFIX | PROTECTED / GOOD | 0+ | BELTED | RWF |
| 3 YEAR OLD CHILD | CHICCO ELETTA | PROTECTED / POOR | 1 | BELTED | FWF |

SAFETY EQUIPMENT

| FRONT SEATBELT PRETENSIONERS | NO | SIDE BODY AIRBAGS | NO | SBR | NO |
|--------------------------------|----|--------------------|----|-------------------|----|
| DRIVER FRONTAL AIRBAG | NO | SIDE HEAD AIRBAGS | NO | ISOFIX ANCHORAGES | NO |
| FRONT PASSENGER FRONTAL AIRBAG | NO | DRIVER KNEE AIRBAG | NO | ABS (4 CHANNEL) | NO |

ADULT OCCUPANT

The protection offered to the driver head was poor due to the hard contact with the steering wheel and for this reason the star capping was applied. Also Diver's neck received poor protection Driver's chest protection was poor due to its high compression, Passenger's chest protection was adequate. Both front passengers' knees could impact with dangerous structures in the dashboard lie the Tran fascia tube. The bodyshell was rated as unstable.

CHILD OCCUPANT

The child seat for the 3 year old child was unable to prevent excessive forward movement during the impact. The dynamic performance of the child restraints was adequate. However, the installation instructions on both child seats were insufficient and not permanently attached to the seat. The recommended CRS did not show incompatibilities with the belt system on the vehicle. This vehicle was not equipped with a passenger airbag.